

LEDERLE LABORATORIES



A Division of AMERICAN CYANAMID COMPANY

PEARL RIVER, NEW YORK 10965

AREA CODE 914 735-5000

NYS 000 001 265

June 3, 1981

U. S. EPA Region 2
Sites Notification
New York, NY 10007

Subject: Notification of Hazardous Waste Site

Dear Sir:

In accordance with the requirements of the Comprehensive Environmental Response, Compensation and Liability Act, enclosed please find a completed "Notification of Hazardous Waste Site" form for American Cyanamid's Lederle Laboratories plant.

In addition to the required form, we have chosen to enclose a supplementary information form which more adequately and properly identifies the activities that have occurred at this facility. We have likewise indicated known releases to the environment as a response to question G specifically because of the spills (items E-H) identified on the supplementary information form. The information contained in this submittal includes a review of the information provided in the Eckhardt Survey.

This submission or any past or future discussion or communication with respect to this matter is not intended to admit liability or to waive any rights.

If you require any clarification of the data presented in our application, please contact Mr. J. P. Vadovic at any time.

Very truly yours,


A. L. Smith
Plant Manager

JPV:kad

217041





✓

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies. *01-688*

810608

NY 5 000 001 265

Zip Code 07470

City Pearl River County Rockland State NY Zip Code 10965

NYD054065909

Phone (914) 735-5000 x. 2437

1981
To (Year)

See Supplementary Sheet

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

1. ☐ Organics
2. ☐ Inorganics
3. ☒ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☒ Acids
7. ☐ Bases
8. ☒ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☒ Other (Specify)
(Wastewater Treatment
sludges) 300

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☒ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☒ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

[illegible][illegible][illegible]

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space, give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

See Supplementary Sheet

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☒ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☒ Other (Specify) (Spills, Open Burning)

Total Facility Waste Amount

cubic feet ~~No Record Estimate 25,000~~

gallons ~~No Record Estimate 225,000~~

Total Facility Area

square feet ~~No Record Estimate 10,000~~

acres ~~10,000~~

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☒ Known ☐ Suspected ☐ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

SEE PLANT MAP

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

American Cyanamid Co.

Name A. L. Smith, Lederle Laboratories

Street No. Middletown Road

City Pearl River State NY Zip Code 10965

Signature

A L Smith

Date 6/3/81

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other